




FIG-3















FIG-12





















IMPROVED REDUCING MACHINE ROTOR ASSEMBLY, etc. Gary M. Bardos 5181.5045.002










FIG-25
















FIG-40









IMPROVED REDUCING MACHINE ROTOR ASSEMBLY, etc. Gary M. Bardos 5181.5045.002







> $\underline{\omega}$ ŏ 8 ð 8 <u>9</u> ŏ 8 ŏ $\overline{\mathbf{c}}$ 8 ŏ 4 8 $\overline{\Omega}$ ŏ 8 $\underline{\alpha}$ ŏ 8 ŏ 8 ŏ <u>Q</u> 8 6 ŏ ŏ $\boldsymbol{\omega}$ ŏ 8 ~ 8 ŏ ဖွ 36 0 X ŏ S ŏ 4 8 ŏ 3 8 ŏ S 8 ŏ g 0 m 4 m 0 r 8 DRIVE (N) 4 (5) \odot

F16-47

O = SPACERS X = HAMMERS






FIG-48

FIG-49








FIG-50